



How to Order - Koncentric Unions

How to Order: Example: 1/2KUT-M		
1/2	KUT	M
Pipe Size (Chart #1)	Configuration (Chart #2)	Special Modifiers (Chart #3)

Chart #1	
Pipe Size	Dash Size
1/4	4
3/8	6
1/2	8
3/4	12
1	16
1-1/4	20
1-1/2	24
2	32

Chart #2	
Configuration	Description
KUT	Pipe Thread Union
KUS	Pipe Socket Weld
KUB	Pipe Butt Weld
KSWU	Tube Socket Weld
KSWG	Tube Socket to SAE Straight Thread
KSWG	Tube Socket to SAE Straight Thread Elbow
RUN	Union Nut
TR	Teflon Snap Ring

Chart #3 Special Modifiers

M	Monel®
R	Tailpiece only
T	Threaded piece only

- Use Pipe size callouts for KUT, KUS, KUB
- Use Dash size callouts for KSWU, KSWG, KSWG
- Dash size is the suffix on the KUN part number. (Example KUN-4)

The Koncentrik union is a four-piece assembly consisting of a threaded piece, tailpiece, union nut, and Teflon seal. The Teflon seal is seated in a precision-machined groove in the male cone shaped tailpiece. By using the chart below, many configurations can be made, by simply matching the threads on the threaded end to the threads on the corresponding nut.

Assembly	Body	Threaded	Tailpiece	Union Nut	Teflon Ring
KUT		KUT-T	KUT-R	KUN	TR
KUS		KUS-T	KUS-R	KUN	TR
KUB		KUB-T	KUB-R	KUN	TR
KSWU		KSWU-T	KSWU-R	KUN	TR
AKSWG	KSWG		KSWU-R	KUN	TR
AKSWG	KSWG		KSWU-R	KUN	TR